

Conversion pouces millimètres

Inches Pouces	Millimètres	Inches Pouces	Millimètres
1/8	3,175	1" 1/2	38,10
3/16	4,763	1" 3/4	44,45
1/4	6,35	2"	50,8
5/16	7,938	2" 1/4	57,15
3/8	9,525	2" 1/2	63,5
7/16	11,112	2" 3/4	69,85
1/2	12,7	3"	76,2
9/16	14,288	3" 1/4	82,55
5/8	15,875	3" 1/2	88,9
11/16	17,462	3" 3/4	95,20
3/4	19,05	4	101,6
7/8	22,225	5	127
15/16	23,812	6	152,4
1	25,4	7	177,8
1" 1/4	31,75	8	203,2